



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 07/07/2014


Reviewed 

Mine Name: Thomas Pit	Permit Number: M/011/0002	Mine Status: Active
Operator Name: Lakeview Rock Products, Inc	Inspection Date: 05/01/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 3:00 PM	Bond Amount: \$142,000
Attendee(s): John Burggraf	Weather: Sunny, Dry	Bond Escalation: 04/01/2011
Inspection Purpose: Routine annual inspection		Prior Inspection: 01/07/2011

Conclusions and Recommendations

It is the recommendation of the Division to grade the floors of the pit to drain to sump sites internal to the mine permit. It is also the recommendation of the Division that the operator interim seed areas that are disturbed, but not fully reclaimed. Interim seeding helps with dust suppression and reduces the chance for weeds to establish in disturbed areas. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Bond escalation was sent out 04/21/2011. Response submitted on August 31, 2011. Bond escalation deficiencies were discussed with the operator at the time of inspection, operator has requested written documentation.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No deficiencies were noted		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No external drainage noted, but weather was dry		
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel was properly contained - see photo		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roads were well maintained and in good condition with dust suppression		
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No concurrent reclamation was noted		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No regrading at the site		
8. <i>Soils</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No soil stockpiles are noted		
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No revegetation was noted		
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
This line is intentionally left blank		

Inspector's Signature: 

CC: Scott Hughes - Lakeview Rock Products

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M011-Davis/M0110002-ThomasPit/Inspections/INSP-03052013.pdf



Overview of the site - looking west



Overview of the site - looking northwest



Product Stockpile



Fuel Storage